

Prepared For:



# ADA COMPLIANCE ASSESSMENT REPORT

FOR

## City of Broken Arrow DOWNTOWN MAIN STREET STREETSCAPE PHASE 3

Prepared By:

### **R.L. SHEARS COMPANY, P.C.** **LANDSCAPE ARCHITECTS**

1 5 2 2 S O U T H C A R S O N A V E N U E  
T U L S A , O K L A H O M A 7 4 1 1 9  
T E L . ( 9 1 8 ) 5 8 2 . 0 6 1 2 F A X ( 9 1 8 ) 5 8 2 . 0 6 1 3  
E M A I L : r s h e a r s @ r l s h e a r s c o . c o m

URBAN DESIGN & STREETSCAPES ● PARK & RECREATION FACILITIES  
MULTI-USE TRAILS ● SITE PLANNING & DESIGN ● MASTER PLANNING

## ADA Compliance Assessment Report

The R.L Shears Company, P.C. conducted an Americans with Disability Act (ADA) compliance assessment as part of the Planning and Scoping Phase of the Broken Arrow Downtown Main Street Streetscape Phase 3 project. The area of study extends from College Street to Fort Worth on Main Street and includes one half block east and west of Main Street to the alleys except on Commercial Street where it extends east to 1st Avenue and west to Ash Avenue. The purpose of this study was to evaluate the ADA conditions of the existing sidewalks based on the requirements and standards included in the 2010 ADA Standards for Accessible Design published by the Department of Justice on September 15, 2012. The study primarily focused on the sidewalk cross slopes, building doorway entry landings, accessible routes, and building doorways.

The assessment was conducted by block and half blocks segments throughout the project area and more specifically by the addresses of each business. In the attached ADA Compliance Assessment Table, the ADA compliance categories evaluated are located in columns across the top of the table and the assessment locations are listed in rows on the left side of the table. The results are oriented horizontally to right of each assessment location.

Sidewalk cross slopes and building doorway landings were evaluated using a “Smart” level that works the same as a typical construction level but displays the percentage of slope on a small LCD display. Sidewalk cross slopes were measured between the back of curb and the building façade in front of each business and building doorway landings were measured outside each doorway perpendicular to the building façade. Sidewalks and doorway landings with cross slopes exceeding 2% are considered non-compliant. Building doorways and entry landings were further evaluated and divided into several categories for analysis.

In addition to cross slope measurements, visual inspection and measurements were used to determine accessible compliance for doorways and doorway landings. Items surveyed include clear space required for maneuvering on either side of doors in order to gain entrance to the building, presence of steps or risers, and changes in level at door thresholds. Inset doorways were separated into their own category and are defined as doors that are set back beyond the building façade. Longitudinal slopes (perpendicular to the door) and cross slopes (parallel to the door) were measured on the sidewalk within setback areas. Additional observations were made with regards to building doorways and building façades that will be used as design aides during the construction document phase of the project.

The results of the ADA compliance assessment show that a large majority of the existing sidewalks within the project area do not comply with the Americans with Disabilities Act. In most cases, the noncompliance is attributed to a failing score in one category and in other cases it is attributed to failing scores in multiple categories. The vast majority of the noncompliance issues for either sidewalks or doorway landings are caused by excessive cross slopes.

The data collected as part of the ADA compliance assessment will be helpful in determining the scope of sidewalk replacement for the Phase III Downtown Main Street Streetscape Proj-

ect. Replacing the noncompliant sidewalks as part of the phase III streetscape improvements will not only reduce the risk of injury to pedestrians and provide better ADA access within the downtown district, but will also provide an opportunity to create more desirable and functional transition with the wider sidewalks planned in the new streetscape design.

**ADA COMPLIANCE ASSESSMENT :: CITY OF BROKEN ARROW DOWNTOWN MAIN STREET STREETScape PHASE III**



**LEGEND :**

- BASIS FOR FAILURE
- BUILDING SET BACK BEYOND RIGHT OF WAY (PRIVATE PROPERTY)

**ASSESSMENT LOCATIONS**

	ADA COMPLIANCE: PASS (P) - FAIL (F)	SIDEWALK CROSS SLOPE (BUILDING TO CURB)	DOORWAY ENTRY LANDING				BUILDING DOORWAY						WIDTH OF ACCESSIBLE ROUTE MINIMUM ACCESSIBLE WIDTH BETWEEN OBSTRUCTIONS (BUILDING TO CURB) (*) - VERTICAL OBSTRUCTION	INSET BUILDING DOORWAY		BUILDING FACADE			CURB HEIGHT PERPENDICULAR TO DOORWAY (TOP OF STEP (TS) - BOTTOM OF STEP (BS))	
			ACCESSIBLE DOORWAY LANDING PROVIDED	RAMP TO LANDING	DOORWAY LANDING CROSS SLOPE (PERPENDICULAR TO DOORWAY)	RISER AT DOORWAY	DOORWAY LOCATED BEYOND RIGHT OF WAY	COMPLIANT THRESHOLD RISE: YES (Y) - NO (N)	SINGLE DOOR	DOUBLE DOOR	DOOR SWING: INSIDE (I) - OUTSIDE (O)	DOOR HINGE: RIGHT (R) - LEFT (L)		DOOR TO STAIRWAY - NON PUBLIC	LONGITUDINAL SLOPE (PERPENDICULAR TO DOORWAY)	CROSS SLOPE (PARALLEL TO DOORWAY)	BUILDING FACADE: MASONRY (M) - WOOD (W)	JOINT BETWEEN SIDEWALK & FACADE		FACADE ATOP SIDEWALK
North Main Street (west side): College St. to Broadway Ave.																				
112 N. Main St. (B.A. PUBLIC SCHOOLS SPECIAL SERVICES CENTER)	P	1.4%					X						7'-3"						4.5"	
106 N. Main St. (ROSS & EUDEY ATTORNEYS AT LAW)	F	3.1%	Y		1.4%			Y	X	I	R		9'-4"						4.2"	
West Broadway Avenue (north side): Main St. to Alleyway																				
West Broadway Avenue (south side): Main St. to Alleyway																				
South Main Street (west side): Broadway Ave. to Commercial St.																				
106 S. Main St. (FINE QUILT & FASHION FABRICS)	F	2.1%	N		3.1%			Y	X	I	L		8'-6"				M	X	5.4"	
108 S. Main St. (ANNA CHRISTY'S SPA-LON)	F	3.5%	N		8.4%			Y	X	O	L		8'-4" / *				M	X	5.5"	
110 S. Main St.	F	3.3%	N		3.0%			Y	X	I	R		8'-8"				M	X	5.4"	
112 S. Main St. (GIRL-FRIENDS EXCESS-ORIES)	F	2.7%	Y		0.3%			Y	X	O	R		9'-3"				M	X	4.68"	
114 S. Main St. (QUAID & ASSOCIATES, LLC.)	P	1.9%	Y		1.9%			Y	X	O	L		7'-9"				M	X	4.68"	
116 S. Main St. (FAMILY BACK CREEK DELI)	F	2.5%	N		2.3%			Y	X	O	L		9'-6"				M	X	4.32"	
116 1/2 S. Main St.	F	2.2%	N		2.2%		X	Y	X	O	R	X	7'-6"	0.4%	0.6%		M	X	5.16"	
118 S. Main St. (ROCK-A-BOW, BABY!)	F	1.4%	N		1.6%			N	X	O	R		8'-10"				M	X	5.76"	
120 S. Main St. (STAR JEWELERS)	F	2.1%	N		1.7%			N	X	O	R		7'-8" / *				M	X	5.76"	
122 S. Main St. (McHUSTON BOOKSELLERS)	F	1.0%	N		2.6%			Y	X	O	L		7'-8"				M		4.56"	
124 S. Main St. (GLAMOUR GOWNS & MORE)	P	0.9%	Y		1.5%			Y	X	O	L		6'-11"				M		4.44"	
West Commercial Street (north side): Main St. to Ash Ave.																				
GLAMOUR GOWNS & MORE (side door)	F	0.4%	N		6.4%			Y	X	O	R		4'-10"				M		X	2.28"
110 W. Commercial St.	F	2.8%	N		5.6%			Y	X	O	L		3'-7"				M		X	2.52"
112 W. Commercial St. (PAULA CHAPMAN GATESWAY VOL. CENTER)	P	0.4%	Y		0.0%			Y	X	O	L		6'-3"				W			5.52"
114 W. Commercial St. (THE ANNE ZARROW GATESWAY CLINIC)	F	0.9%	N		4.1%			Y	X	I	L		6'-3"				W			9"
West Commercial Street (south side): Main St. to Ash Ave.																				
123 W. Commercial St. (FAMILY SECURITY MORTGAGE)	F	2.5%	N		3.2%			Y	X	O	L		4'-7"				M	X		1"
121 W. Commercial St. (ALLIANCE LEGAL COUNSEL P.C.)	F	7.0%	N		5.4%			Y	X	O	R		2'-8"				M	X		7.68"
119 W. Commercial St. (BROKEN ARROW LODGE #243 AF & AM)	F	0.8%	N		6.3%			N	X	O	R		6'-0"				M	X		7.8"
117 W. Commercial St.	F	2.4%	N		9.6%			N	X	O	L		5'-7"				M	X		7.8"
109 W. Commercial St. (LAPTOPS FOR LESS)	F	3.1%	N		8.6%			N	X	I	L		3'-9"				W	X		8.28"

**ADA COMPLIANCE ASSESSMENT :: CITY OF BROKEN ARROW DOWNTOWN MAIN STREET STREETScape PHASE III**



**LEGEND :**

- BASIS FOR FAILURE
- BUILDING SET BACK BEYOND RIGHT OF WAY (PRIVATE PROPERTY)

**ASSESSMENT LOCATIONS**

	ADA COMPLIANCE: PASS (P) - FAIL (F)	SIDEWALK CROSS SLOPE		DOORWAY ENTRY LANDING			BUILDING DOORWAY						WIDTH OF ACCESSIBLE ROUTE	INSET BUILDING DOORWAY		BUILDING FACADE			CURB HEIGHT
		SIDEWALK CROSS SLOPE (BUILDING TO CURB)	ACCESSIBLE DOORWAY LANDING PROVIDED	RAMP TO LANDING	DOORWAY LANDING CROSS SLOPE (PERPENDICULAR TO DOORWAY)	RISER AT DOORWAY	DOORWAY LOCATED BEYOND RIGHT OF WAY	COMPLIANT THRESHOLD RISE: YES (Y) - NO (N)	SINGLE DOOR	DOUBLE DOOR	DOOR SWING: INSIDE (I) - OUTSIDE (O)	DOOR HINGE: RIGHT (R) - LEFT (L)	DOOR TO STAIRWAY - NON PUBLIC	MINIMUM ACCESSIBLE WIDTH BETWEEN OBSTRUCTIONS (BUILDING TO CURB) (*) - VERTICAL OBSTRUCTION	LONGITUDINAL SLOPE (PERPENDICULAR TO DOORWAY)	CROSS SLOPE (PARALLEL TO DOORWAY)	BUILDING FACADE: MASONRY (M) - WOOD (W)	JOINT BETWEEN SIDEWALK & FACADE	FACADE ATOP SIDEWALK
107 W. Commercial St. (RUSSEL D. PETERSON ATTORNEYS)	F	5.3%	N		7.8%		Y	X		I	R		4'-0"			W		X	7.68"
MAIN STREET TAVERN (side door)	F	4.1%	N		0.6%	X	Y	X		O	L		4'-9"			M	X		7.32"
South Main Street (west side): Commercial St. to Dallas St.																			
200 S. Main Street (MAIN STREET TAVERN)	F	1.9%	N		4.8%		Y	X		O	R		4'-2"			M	X		5.88"
202 S. Main Street	F	2.8%	N		7.3%		N	X		O	R		6'-2"			M	X		7.56"
204 S. Main Street	P	0.7%	Y		1.7%		Y	X		O	L		6'-2"			M	X		6.24"
206 S. Main Street (SEASONS HOME FRAGRANCE & DÉCOR)	F	4.6%	Y		0.6%		Y	X		O	L		4'-0"			M	X		6.24"
210 S. Main Street (FURNITURE & DESIGN SOLUTIONS)	F	3.2%	N		> 2%		X	Y	X		O	R	4'-6"	12.2%	0.3%	M	X		6.6"
212 S. Main Street	F	3.1%	N		3.4%		X	Y		X	I	R/L	7'-4"	3.8%	0.2%	M	X		7.44"
216 S. Main Street	F	2.7%	N		2.7%		X	Y	X		I	R	6'-2"	1.3%	0.6%	W/M	X		6"
218 S. Main Street	F	3.0%	N	X	3.3%	X	X	Y	X		O	R	7'-5"	1.8%	0.6%	W	X		6.6"
222 S. Main Street	F	3.2%	N	X	2.7%	X	X	Y	X		O	L	5'-5"	1.3%	0.2%	W	X		6.6"
224 S. Main Street (ON THE CORNER - GIFTS, GALLERY & DECOR)	F	3.9%	N		7.3%		Y	X		I	L		4'-2"			M	X		6.72"
West Dallas Street (north side): Main St. to Alleyway.																			
West Dallas Street (south side): Main St. to Alleyway.																			
AVB Bank (side door)	F	3.8%	N		3.7%		X	Y		X	O	R/L	9'-10"	2.7%	0.4%	M	X	X	4.8"
South Main Street (west side): Dallas St. to El Paso St.																			
302 S. Main Street (AVB BANK - north door)	F	3.7%	N		1.5%		N		X	O	R/L		5'-6"			M	X	X	6.36"
302 S. Main Street (AVB BANK - south door)	F	4.4%	N		3.4%		X	Y		X	O	R/L	6'-0"	13.0%	0.4%				7.32"
West El Paso Street (north side): Main St. to Alleyway.																			
West El Paso Street (south side): Main St. to Alleyway.																			
BROKEN ARROW HISTORICAL SOCIETY (side door)	F	2.3%	N		1.3%		Y	X		O	L		4'-5"			M	X		9"
South Main Street (west side): El Paso St. to Ft. Worth St.																			
400 S. Main Street (BROKEN ARROW HISTORICAL SOCIETY)	F	0.8%	N		0.7%		Y	X		O	R		4'-5"			M	X		6.96"
BROKEN ARROW HISTORICAL SOCIETY (side door)	F	3.3%	N	X	1.7%		Y	X		O	R		3'-4"			M	X		5.64"
South Main Street (east side): Ft. Worth St. to El Paso St.																			
407 S. Main Street (ADDITIVE SYSTEMS INC.)	F	1.9%	N		8.9%		Y		X	O	R/L		7'-0"			W	X		6.72"
405 S. Main Street (STATE FARM INSURANCE - BROWN AGENCY)	F	2.4%	N		1.8%		X	Y	X		O	R/L	5'-6"	2.3%	0.6%	M	X		5.28"

**ADA COMPLIANCE ASSESSMENT :: CITY OF BROKEN ARROW DOWNTOWN MAIN STREET STREETScape PHASE III**



**LEGEND :**

- BASIS FOR FAILURE
- BUILDING SET BACK BEYOND RIGHT OF WAY (PRIVATE PROPERTY)

**ASSESSMENT LOCATIONS**

	ADA COMPLIANCE: PASS (P) - FAIL (F)	SIDEWALK CROSS SLOPE		DOORWAY ENTRY LANDING			BUILDING DOORWAY						WIDTH OF ACCESSIBLE ROUTE	INSET BUILDING DOORWAY		BUILDING FACADE			CURB HEIGHT	
		SIDEWALK CROSS SLOPE (BUILDING TO CURB)	ACCESSIBLE DOORWAY LANDING PROVIDED	RAMP TO LANDING	DOORWAY LANDING CROSS SLOPE (PERPENDICULAR TO DOORWAY)	RISER AT DOORWAY	DOORWAY LOCATED BEYOND RIGHT OF WAY	COMPLIANT THRESHOLD RISE: YES (Y) - NO (N)	SINGLE DOOR	DOUBLE DOOR	DOOR SWING: INSIDE (I) - OUTSIDE (O)	DOOR HINGE: RIGHT (R) - LEFT (L)	DOOR TO STAIRWAY - NON PUBLIC	MINIMUM ACCESSIBLE WIDTH BETWEEN OBSTRUCTIONS (BUILDING TO CURB) (*) - VERTICAL OBSTRUCTION	LONGITUDINAL SLOPE (PERPENDICULAR TO DOORWAY)	CROSS SLOPE (PARALLEL TO DOORWAY)	BUILDING FACADE: MASONRY (M) - WOOD (W)	JOINT BETWEEN SIDEWALK & FACADE	FACADE ATOP SIDEWALK	CURB HEIGHT PERPENDICULAR TO DOORWAY (TOP OF STEP (TS) - BOTTOM OF STEP (BS))
East El Paso Street (south side): Main St. to Alleyway.																				
East El Paso Street (north side): Main St. to Alleyway.																				
112 E. El Paso St. (PHOENIX DELIVERY)	F	5.5%	N	10.4%			Y	X	O	L			5'-1"			M	X	X		7.56"
110 E. El Paso St.	F	3.3%	N	9.4%			Y	X	O	R			5'-0"			M	X			7.32"
108 E. El Paso St.	F	4.5%	N	7.2%			N	X	I	L			5'-0"			M	X			6.84"
104 E. El Paso St.	F	1.3%	N	7.2%			N	X	O	L			5'-0"			M	X			6.84"
102 E. El Paso St.	F	2.9%	N	7.1%			N	X	I	L			4'-10"			M	X			6.72"
SORELLA SALON (side door)	F	1.6%	N	7.6%			Y	X	I	R			4'-10"			M	X			6"
South Main Street (east side): El Paso St. to Dallas St.																				
323 S. Main St. (SORELLA SALON)	F	2.5%	N	6.1%			Y	X	I	R			8'-0"			M	X			3.36"
311 S. Main St. (TULSA FEDERAL CREDIT UNION)	F	3.3%	N	3.7%			X	Y	X	O	R		7'-2"	6.7%	0.7%	M	X			4.92"
East Dallas Street (south side): Main St. to Alleyway																				
East Dallas Street (north side): Main St. to Alleyway																				
114 E. Dallas St. (side door)							X						4'-0"							
114 E. Dallas St.							X						4'-10"							
FAMILY VISION CARE (side door)							X						3'-11"							
South Main Street (east side): Dallas St. to Commercial St.																				
227 S. Main Street (FAMILY VISION CARE)	F	1.9%	N	2.4%			Y	X	I	R			4'-0"			M	X			7.44"
223 S. Main Street (BELLA VITA)	F	3.2%	N	3.0%			Y	X	O	L			4'-2"			M	X			8.52"
219 S. Main Street (FIESTA MAMBO)	F	2.8%	N	11.6%			Y	X	O	L			3'-7"			M	X			9.24"
217 S. Main Street (SPIRIT STEEL GUITAR)	F	4.2%	N	7.6%			N	X	I	L			3'-7"			M	X			8.28"
215 S. Main Street (DIGITAL PUBLISHING AND SCANNING)	F	2.2%	N	2.8%			X	Y	X	O	L		6'-4"	0.5%	1.8%	M	X			8.04"
213 S. Main Street (ARROW FLOWERS AND GIFTS)	F	3.3%	N	14.1%			N	X	O	R			5'-11" / *			M	X			8.52"
211 S. Main Street (YOUR DESIGN)	F	2.8%	N	2.3%			X	Y	X	O	L		6'-9"	1.3%	0.5%	M	X			8.76"
209 1/2 S. Main Street	F	3.0%	N	3.6%			Y	X	I	R			6'-9"			W/M	X			8.76"
209 S. Main Street	F	3.8%	N	8.3%			N	X	O	L			8'-0"			W/M	X			8.64"
207 S. Main Street (MAIN STREET STUDIOS)	F	4.1%	N	9.5%			N	X	O	L			3'-7"			M	X			8.16"
205 S. Main Street (NOUVEAU ATELIER De CHOCOLAT)	F	1.6%	N	1.9%			X	Y	X	I	R/L		3'-6"	2.8%	0.7%	M	X			6.84"

**ADA COMPLIANCE ASSESSMENT :: CITY OF BROKEN ARROW DOWNTOWN MAIN STREET STREETScape PHASE III**



**LEGEND :**

- BASIS FOR FAILURE
- BUILDING SET BACK BEYOND RIGHT OF WAY (PRIVATE PROPERTY)

**ASSESSMENT LOCATIONS**

	ADA COMPLIANCE: PASS (P) - FAIL (F)	SIDEWALK CROSS SLOPE		DOORWAY ENTRY LANDING				BUILDING DOORWAY						WIDTH OF ACCESSIBLE ROUTE		INSET BUILDING DOORWAY			BUILDING FACADE			CURB HEIGHT		
		SIDEWALK CROSS SLOPE (BUILDING TO CURB)	ACCESSIBLE DOORWAY LANDING PROVIDED	RAMP TO LANDING	DOORWAY LANDING CROSS SLOPE (PERPENDICULAR TO DOORWAY)	RISER AT DOORWAY	DOORWAY LOCATED BEYOND RIGHT OF WAY	COMPLIANT THRESHOLD RISE: YES (Y) - NO (N)	SINGLE DOOR	DOUBLE DOOR	DOOR SWING: INSIDE (I) - OUTSIDE (O)	DOOR HINGE: RIGHT (R) - LEFT (L)	DOOR TO STAIRWAY - NON PUBLIC	MINIMUM ACCESSIBLE WIDTH BETWEEN OBSTRUCTIONS (BUILDING TO CURB) (*) - VERTICAL OBSTRUCTION	LONGITUDINAL SLOPE (PERPENDICULAR TO DOORWAY)	CROSS SLOPE (PARALLEL TO DOORWAY)	BUILDING FACADE: MASONRY (M) - WOOD (W)	JOINT BETWEEN SIDEWALK & FACADE	FACADE ATOP SIDEWALK	CURB HEIGHT PERPENDICULAR TO DOORWAY (TOP OF STEP (TS) - BOTTOM OF STEP (BS))				
203 S. Main Street	F	3.1%	N		3.6%		X	Y	X		O	L				6'-6" / *	0.2%	0.5%	M	X			6.72"	
201 S. Main Street (DOOLEY'S ANGUS INN STEAK HOUSE)	F	3.7%	N		4.4%		X	Y	X		O	L				6'-0"	2.1%	0.4%	M	X			5.16"	
East Commercial Street (south side): Main St. to 1st St.																								
DOOLEY'S ANGUS INN STEAK HOUSE (side door)	F	3.0%	Y		0.9%			N	X		O	R				5'-8"			M	X			5.76"	
DOOLEY'S ANGUS INN STEAK HOUSE (side door)	P	1.9%	Y		1.7%		X	Y	X		O	L				5'-8" / *	0.6%	0.1%	M	X			5.76"	
107 E. Commercial St.	F	2.5%	Y		1.4%			Y	X		I	L				5'-9" / *			M	X			5.76"	
109 E. Commercial St.	P	1.5%	Y		1.7%			Y	X		I	L				5'-10"			M	X			5.16"	
111 E. Commercial St. (SANDERS BARBER SHOP)	F	3.2%	N		3.0%			Y	X		I	L				5'-10"			M	X			3.48"	
East Commercial Street (north side): Main St. to 1st St.																								
120 E. Commercial St. (FIRST NATIONAL BANK & TRUST)(east door)	F	2.6%	N		2.9%		X	Y		X	O	R/L				5'-0"	1.8%	0.2%	M	X			7.08"	
120 E. Commercial St. (FIRST NATIONAL BANK & TRUST)(west door)	F	3.2%	N		4.7%		X	Y	X		O	L				6'-4"	2.7%	0.5%	M	X			7.08"	
118 E. Commercial St. (THE ASSEMBLY)	F	5.2%	N		4.5%			Y	X		O	L				6'-4"			M	X			6.24"	
FIRST NATIONAL BANK & TRUST (side door)							X	Y								8'-4"								
FIRST NATIONAL BANK & TRUST (south door)	F	3.1%	Y		0.5%		X	Y		X	O	R/L				6'-9"	0.9%	0.4%	M	X			5.28"	
South Main Street (east side): Commercial St. to Broadway Ave.																								
121 S. Main Street (FIRST NATIONAL BANK & TRUST)	F	2.5%	N		1.7%		X	Y		X	O	R/L				5'-2"	4.5%	3.2%	M	X			6"	
East Broadway Avenue (south side): Main St. to Alleyway																								
East Broadway Avenue (north side): Main St. to Alleyway																								
ALLISON & ASSOCIATES REALTORS (side door)	F	1.5%	N		3.3%	X		N	X		I	R				6'-9"			M	X			5.76"	
South Main Street (east side): Broadway Ave. to College St.																								
101 N. Main St. (ALLISON & ASSOCIATES REALTORS)	F	4.5%	Y		1.1%			Y	X		O	L				4'-10"			M	X			8.88" TS 5.04" BS	
103 N. Main St. (TED L. MOORE ATTORNEY AT LAW)	F	3.5%	N		2.2%			N	X		I	L				7'-0"			M	X			9.12" TS 5.16" BS	
105 N. Main St. (QUICKSILVER GRAPHICS AND PRINTING)	F	3.1%	N		2.7%			N	X		I	L				7'-0"			M	X			9" TS 5.4" BS	
107 N. Main St. (STONE CREEK DAY SPA)(south door)	F	2.3%	N		3.1%			Y	X		I	L				3'-9"			M	X			5.04" BS	

